

Fire

053 027 A		2026 PIKE County Board of Assessors				4/13/2026 2:42:28 PM Acct # 3767 danyeah	
Owner Information		General Property Information				Values	
CONNER DEBRA 1353 DREW ALLEN RD WILLIAMSON, GA 30292		SITUS		1358 DREW ALLEN RD		Imp Val	18,534
		LEGAL		1358 DREW ALLEN ROAD		Acc Val	857
		Tax District		UNINCORPORATED	GMD	Homestead	S0
		Total Acres		4.14	LL	255	No Covenant
		Zoning			LD	01	Acc/Des
		Unit			Return Value		0
							2025 : 60,690
							2024 : 61,594
							2023 : 61,594
							2022 : 61,594
							81,331
TOPOGRAPHY - .00 CORNER - .00 VIEW - .00 WATER - .00 TRANSITIONAL - .00 NEIGHBORHOOD - .00 OTHER - .90 - 1.00							
OLD ADDRESS 384							


SALES INFORMATION								
Grantee	Grantor	Date	Deed Book	Plat Book	Saleprice	CS	Mkt Value	Reason
CONNER DEBRA	SCOTT LUCINDA	03/01/2019	1164 245	008 288		0 R1		0 QC
HALL LUCINDA F AKA HALL CINDY	HALL STEVE L AKA HALL STEVE	07/16/1993	147 085	008 288		0 R1		0 MH
HALL STEVE & CINDY	STONAKER ALICE M	03/14/1989				0 R1		0 KN

LAND INFORMATION					
CS	Land Use	Productivity	ACRES	Unit Value	UnAdj Value
R3	SMALL PARCEL	3	4.14	1,000	4,140

ACCESSORY IMPROVEMENTS - 053 027 A														
CS	Descrip	Dim1	Dim2	Units	Year	Grade	Depr	Ovr D	Pcom	Func	Econ	Neigh	IDnits	Value
R6	Metal Bldg - Low	8	12	96	2013	1.00	0.98	0.00	1.00	1.00	1.00		0.00	857

RES IMP - 053 027 A			
Impr Key	4502	Tip Out/Addn	0 x 0 0
PIN		Lot Number	
Account #	243	RCN	52,948
Serial #		Eff Year Built	1989
Decal Year		Phy Depr	0.33
Decal Number		Ovr Phy Depr	0.00
Year Built / Size	1989 28 x 66	Func Obsol	1.00
HUD Tag		Econ Obsol	1.00
MFG	HOMESTEAD HOMES I	Value	17,473
Model	CRYSTAL EDITION	Value Type	MKT/COST
Class	AV	Addon Value	1,061
Exterior Wall	Vinyl Siding	FMV	18,534
Roofing	Asphalt Shingle	NADA Condition	A
Foundation	Masonry		
Heat / Air			
Fireplace			
Condition	Average		
Full Baths	2		
Half Baths	0		
Story Height	1		

Mfg Housing Add-ons						
Type	Size	Area	YEAR	DEPR	GRADE	VALUE
Open Porch	5x24	120	1989	0.52	1.00	1,061



Incident Location: 1358 DREW ALLEN Road
Incident City, State, Postal Code: WILLIAMSON, GA 30292

Incident Date: 02/05/2026



Deploy NERIS Print Report

Details Reported by Dispatch

Incident Number: 26000187
Dispatch Point: 33.128595,-
84.369121

Dispatch Timeline

Call Arrival: 02/05/2026
09:24:38
Call Answered: 02/05/2026
09:24:38
Call Created: 02/05/2026
09:24:38
Alarm: 02/05/2026
09:26:32
First Unit Arrival: 02/05/2026
09:31:26
Incident Clear: 02/05/2026
13:55:11
In Service: 02/05/2026
13:55:11

Location as Reported by Dispatch

Dispatched Location: 1358 DREW ALLEN Road
City, State, Postal Code: WILLIAMSON, GA 30292

Unit Response as Reported by Dispatch

Dispatch Unit Responses

Dispatch Unit Call Sign	Dispatch Unit Dispatch Time	Dispatch Unit Enroute to Scene Time	Dispatch Unit on Scene Time	Dispatch Unit Incident Clear Time	Dispatch Apparatus or Resource in Service Date Time
347	09:26:32	09:26:33		12:08:06	12:08:06
8ENG	09:34:00	09:34:01	09:40:48	12:08:06	12:08:06
546	09:27:56	09:27:57		12:08:06	12:08:06

Incident Details

Incident Date: 02/05/2026

Incident Point: 33.128595,-
84.369121

Incident ID: 26000187

Primary Incident Type: Fire - Structure Fire - Structural Involvement
Additional Incident Types: Medical - Injury / Trauma - Burns / Explosion

Response Mode To Scene: Emergency

Primary Station: Zebulon (7)

Shifts or Platoon: Combination

Fire Service Casualties / Rescues: 0

People Present: Yes

Civilian Casualties / Rescues: 2

People Displaced: 4

Animals Rescued: 0

Displaced People Cause: Fire; Smoke; Utilities; Hazardous Situation;
Water

Incident Timeline

Incident Number: 26000187

Incident Date: 02/05/2026 Page 1 of 6

Incident Location: 1358 DREW ALLEN Road
Incident City, State, Postal Code: WILLIAMSON, GA 30292

Incident Date: 02/05/2026

Alarm: 02/05/2026
09:26:32
First Unit Arrival: 02/05/2026
09:31:26
Command Established: 02/05/2026
09:32:00
Sizeup Completed: 02/05/2026
09:34:00
Incident Clear: 02/05/2026
13:55:11
In Service Date Time: 02/05/2026
13:55:11

Water On Fire: 02/05/2026
09:36:00
Fire Knocked Down: 02/05/2026
10:00:00
Suppression Complete: 02/05/2026
13:30:00
Fire Under Control: 02/05/2026
10:12:00

Incident Location

Zone Number: Sta6 **District:** 6
Incident Location Type: Street address
Incident Location: 1358 DREW
ALLEN Road
City, State, Postal Code: WILLIAMSON, GA 30292-

Incident Location Use

Location Use Type: Residential - Detached Single Family Dwelling
Incident Location In Use: Yes (Occupied)
Location Used as Intended: Yes

Incident Actions

Incident Action Taken: Command and Control - Establish Incident
Command; Command and Control - Notify Other
Agencies; Command and Control - Incident
Assessment Completed; Emergency Medical
Care - Provide Advanced Life Support;
Investigation; Personnel Contamination
Reduction - PPE Washed Post-Incident; Salvage
And Overhaul; Search Structure - Door Initiated
Search; Suppression - Structural Fire Suppression
- Exterior and Interior

Incident Authorization

Member Making Report - Signature: Gilham, Kevin

Officer in Charge - Signature: Wilkerson,
Bobby

Member Making Report: 54243

Officer in Charge: 22420

Incident Narratives

Primary Narrative: Engine Seven, Brush Truck Seven, QRV Seven and any other fire personal in the area were dispatched to the above address in reference to a possible structure fire. Engine One, Engine Eight, Tanker Eight, 101, 103, 103, 502, and 549 along with the other units all responded to the call. While responding to the call dispatch advised that all occupants were out of the house but had some smoke inhalation. Dispatch also advised it was a working structure fire.

Upon arrival we located a double wide mobile home with fire and smoke showing from the B and C side of the structure. All units went to work on extinguishing the fire. A size up was completed, command established, and we were in a offensive mode of operation. A 1.75 inch hose line was pulled to extinguish the fire and a second was pulled for backup. The water supply was done by tanker shuttle and tank water. The fire was extinguished and salvage and overhaul was completed. The fire was investigated by 502 and the State Fire Marshall. Two occupants of the house were transported by Med Six and Seven to the hospital for burns and smoke inhalation. Once all operations were completed, all equipment was picked up and placed back in service.

Incident Location: 1358 DREW ALLEN Road
Incident City, State, Postal Code: WILLIAMSON, GA 30292

Incident Date: 02/05/2026

All units back in service.

Additional Narrative

Additional Narratives	Authored By	Authored Date
O&C narrative:	Jeremy Strader 502	16:15:00
A reported structure fire was called in to 911 at approximately 0925 by a Laurie Rawlins. She stated that her residence was on fire and that herself, her sister (Debra Rawlins), and her dog were out of the structure. No other individuals were reported to be in the structure. After donning the appropriate protective equipment and determining the possible hazards, I began the investigation by performing a 360 of the structure and noted where damage was from least to most. I noted that the majority of the damage was located on the Charlie side, closest to the B/C corner, with damage reducing from there out. A V-Shaped burn pattern was noted at a Charlie side window closest to the B/C corner with significant mass loss to the structure and supports around it. Very little damage was noted on the C/D corner, Delta side, and A/D corner. Further investigation of the exterior showed an extension cord away from the structure that was damaged with the male end appearing to be melted into the female portion of an indoor receptacle. It was reported by bystanders on scene that the extension cord was ran from the aforementioned window to a camper in the backyard. I received mixed reports stating that the cord was used to run the entire camper and some stating that it was only used to run a radio. I proceeded to focus more on the area of origin and located a receptacle directly beneath the noted v-pattern that was completely destroyed with significant fire damage to it and the surrounding wires. Less damage was noted as you moved down the wire to each side. With the patterns noted, the damage to the structure, evidence located and interviews of fire crews and bystanders on the scene, I believe the origin of the fire was the receptacle located below the window on the charlie side closest to the bravo side. The cause of the fire was an issue with the extension cord which may have caused an arc or spark and generated enough heat to being the fire. I believe this to be Unintentional and electrical in nature.		

Unit Response

<u>Incident Unit Responses</u>										
Unit Call Sign	Apparatus ID	Unit Staffing Reported	Apparatus Action	Unit Dispatch Time	Unit Enroute to Scene Time	Unit on Scene Time	Unit Incident Clear Time	Apparatus or Resource In Service Date Time	Unit Response Mode	Unit Transport Mode
8TNK	8TNK	1	Provide Equipment - Provide Special Equipment	09:26:32	09:26:33	09:40:00	12:08:06	12:08:06	Emergent	

Incident Unit Response Personnel									
Personnel Name/ID		Personnel Rank Or Grade	Personnel Role	Personnel Level	Personnel Pay Rate	Personnel Time In	Personnel Time Out	Personnel Hours Spent	
McAleer, Hugh		Lieutenant	Driver	Firefighter I	15	02/05/2026 09:26:32	02/05/2026 12:08:06	1	
1ENG 1ENG		1	Suppression - Structural Fire Suppression - Exterior and Interior	09:34:00	09:34:01	09:40:48	12:08:06	12:08:06	Emergent

Incident Location: 1358 DREW ALLEN Road
Incident City, State, Postal Code: WILLIAMSON, GA 30292

Incident Date: 02/05/2026

Unit Call Sign	Apparatus ID	Unit Staffing Reported	Apparatus Action	Unit Dispatch Time	Unit Enroute to Scene Time	Unit on Scene Time	Unit Incident Clear Time	Apparatus or Resource In Service Date Time	Unit Response Mode	Unit Transport Mode
----------------	--------------	------------------------	------------------	--------------------	----------------------------	--------------------	--------------------------	--	--------------------	---------------------

Incident Unit Response Personnel

Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level	Personnel Pay Rate	Personnel Time In	Personnel Time Out	Personnel Hours Spent	
Jackson, Keith	Lieutenant	Officer	Firefighter II	15	02/05/2026 09:34:00	02/05/2026 12:08:06	1	
8ENG 8ENG	1	Suppression - Structural Fire Suppression - Exterior and Interior	09:27:56	09:27:57	09:40:00	12:08:06	12:08:06	Emergent

Incident Unit Response Personnel

Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level	Personnel Pay Rate	Personnel Time In	Personnel Time Out	Personnel Hours Spent	
Caron, Christopher	Fire Fighter 1 / EMT	Driver	Firefighter II	15	02/05/2026 09:27:56	02/05/2026 12:08:06	1	
549	549	1	Suppression - Structural Fire Suppression - Exterior and Interior	09:26:32	09:40:00	13:55:11	15:22:55	Non Emergent

Incident Unit Response Personnel

Personnel Name/ID		Personnel Rank Or Grade	Personnel Role	Personnel Level	Personnel Pay Rate		Personnel Hours Spent
Gilham, Mason		FF2/EMT	Driver	Firefighter II	15		1
7QRV	7QRV	1	Suppression - Structural Fire Suppression - Exterior and Interior	09:26:32	09:31:26	13:55:11 13:55:11	Emergent

Incident Unit Response Personnel

Personnel Name/ID			Personnel Rank Or Grade	Personnel Role	Personnel Level			Personnel Hours Spent
Tyree, Owen			FF/EMT	Driver	Firefighter II			1
7BRU	7BRU	1	Suppression - Structural Fire	09:26:32	09:31:26	13:55:11	13:55:11	Emergent
			Suppression - Exterior and Interior					

Incident Unit Response Personnel

Personnel Name/ID			Personnel Rank Or Grade	Personnel Role	Personnel Level		Personnel Hours Spent	
Blount, Doug			FF2	Driver	Firefighter II		1	
7ENG	7ENG	1	Suppression - Structural Fire Suppression - Exterior and Interior	09:26:32	09:31:26	13:55:11	13:55:11	Emergent

Incident Location: 1358 DREW ALLEN Road
Incident City, State, Postal Code: WILLIAMSON, GA 30292

Incident Date: 02/05/2026

Unit Call Sign	Apparatus ID	Unit Staffing Reported	Apparatus Action	Unit Dispatch Time	Unit Enroute to Scene Time	Unit on Scene Time	Unit Incident Clear Time	Apparatus or Resource In Service Date Time	Unit Response Mode	Unit Transport Mode
----------------	--------------	------------------------	------------------	--------------------	----------------------------	--------------------	--------------------------	--	--------------------	---------------------

Incident Unit Response Personnel

Personnel Name/ID	Personnel Role	Personnel Level	Personnel Hours Spent
Gilham, Kevin	Driver	Firefighter II	1
101	101	1	Command and Control - Establish Incident Command
		09:26:32	09:31:26 13:55:11 13:55:11 Emergent

Incident Unit Response Personnel

Personnel Name/ID			Personnel Rank Or Grade	Personnel Role	Personnel Level			Personnel Hours Spent
Wilkerson, Bobby			Chief	Officer	Firefighter II			1
502	502	1	Suppression - Structural Fire Suppression - Exterior and Interior	09:26:32	09:31:26	13:55:11	13:55:11	Non Emergent

Incident Unit Response Personnel

Personnel Name/ID			Personnel Role	Personnel Level	Personnel Pay Rate		Personnel Hours Spent
Strader, Jeremy			Driver	Firefighter II	15		1
102	102	1	Suppression - Structural Fire Suppression - Exterior and Interior	09:26:32	09:31:26	13:55:11	13:55:11 Emergent

Incident Unit Response Personnel

Personnel Name/ID			Personnel Rank Or Grade	Personnel Role	Personnel Level	Personnel Pay Rate		Personnel Hours Spent
Neath, Douglas			Deputy Chief of Operations	Officer	Firefighter II	15		1
103	103	1	Suppression - Structural Fire Suppression - Exterior and Interior	09:26:32	09:31:26	13:55:11	13:55:11	Non Emergent

Incident Unit Response Personnel

Personnel Name/ID	Personnel Role	Personnel Level	Personnel Hours Spent
Poss, Steven	Officer	Firefighter II	1
859	859	1	Provide Services - Provide Apparatus/Water
		10:32:38	12:19:03 12:19:14 Non Emergent Non Emergent

Incident Unit Response Personnel

Personnel Name/ID	Personnel Role	Personnel Level	Personnel Pay Rate
McAleer, Kathy			15
851	851	1	Provide Services - Provide Apparatus/Water
		09:39:27	12:20:53 12:20:01 Non Emergent Non Emergent

Incident Location: 1358 DREW ALLEN Road
Incident City, State, Postal Code: WILLIAMSON, GA 30292

Incident Date: 02/05/2026

Unit Call Sign	Apparatus ID	Unit Staffing Reported	Apparatus Action	Unit Dispatch Time	Unit Enroute to Scene Time	Unit on Scene Time	Unit Incident Clear Time	Apparatus or Resource In Service Date Time	Unit Response Mode	Unit Transport Mode
----------------------	-----------------	------------------------------	---------------------	--------------------------	--	--------------------------	-----------------------------------	--	--------------------------	---------------------------

Incident Unit Response Personnel

Personnel Name/ID	Personnel Role	Personnel Level	Personnel Pay Rate
Totten, Teresa			15

Fire Details

Fire Location Type: Structure

Fire Investigation Needed: Yes

Fire Water Supply: Water Tender
Shuttle

Fire Investigation Type: Investigated By
State Fire
Marshal;
Investigated By
Arson Fire
Investigator

Structure Fire

Fire Progression Evident: Yes

Fire Arrival Condition: Smoke Fire
Showing

Fire Floor Of Origin: 1

Fire Room Of Origin Type: Bedroom

Fire Damage Type: Major Damage

Structure Fire Cause: Electrical

Casualty/Rescue

People Involved

Risk Reduction

Smoke Alarm Presence: Not Present

Fire Alarm Presence: Not Present

Other Alarm Presence: Not Present

Fire Suppression

Fire Suppression Presence: Not Present

Incident Number: 26000187

Incident Date: 02/05/2026